

List of Current and Effective ClassNK Technical Information

Total : 568 issues

| Tec No. | Subject | Date of Issue | Contact |
|---------|--|---------------|---------|
| 1183 | Requirements for maintenance, thorough examination, operational testing, overhaul and repair of lifeboats and rescue boats, launching appliances and release gear | 2019/06/24 | SVD |
| 1182 | Revision of format of Certificate of Classification (Abolishment of Certificate of Installations Registration / Incorporation of Certificate of Installations Registration into Certificate of Classification) | 2019/06/18 | CLD |
| 1181 | Graphical symbols for Fire Control Plans onboard the Cook Islands flagged ships | 2019/04/19 | EQD |
| 1180 | Introduction to the Outcomes of MSC 100 | 2019/04/01 | XAD |
| 1179 | Sample and appraisal services for a ship implementation plan in preparation for the 0.50% sulphur limit for fuel oils from 2020 | 2019/03/29 | MCD |
| 1178 | Two way portable radio apparatus for fire fighter's communication for the Cook Islands flag vessels | 2019/03/19 | EQD |
| 1177 | Emergency escape breathing devices (EEBDs) onboard the Panama flag vessels | 2019/02/27 | EQD |
| 1176 | Graphical symbols for Fire Control Plans onboard the Maltese flagged ships | 2019/02/22 | EQD |
| 1175 | Introduction to the outcomes of MEPC 73 | 2019/02/08 | XAD |
| 1174 | Additional information on Chinese regulations related to the sulphur content of fuel oil on or after 1 January 2019 | 2019/01/28 | TSD |
| 1173 | Ban the use of open-loop scrubbers within Port of Fujairah | 2019/01/25 | TSD |
| 1172 | ----- No English version ----- | 2019/01/08 | SMD |
| 1171 | Expansion of applicable areas subject to regulations on the sulphur content of fuel oil within Chinese emission control areas starting on 1 January 2019 | 2018/12/28 | TSD |
| 1170 | Commencement of the EU Regulation on Ship Recycling | 2018/12/28 | SMD |
| 1169 | PSC Joint Information Campaign on "Global 2020 Sulphur CAP Compliance" | 2018/12/28 | SVD |
| 1168 | Fire fighter's communication for vessels flying the Greek Flag | 2018/12/27 | EQD |
| 1167 | Fuel regulations in Hong Kong waters on or after 1 January 2019 | 2018/11/27 | TSD |
| 1166 | Survey and Certification of Polar Code | 2018/11/09 | HLD |
| 1165 | Ballast Water Management Convention for Panama flagged ships (Revision) | 2018/10/02 | CLD |
| 1164 | Regulations on sulphur content of fuel oil within the ECAs of Yangtze River Delta on or after 1 October 2018 | 2018/09/28 | TSD |
| 1163 | Regulations on sulphur content of fuel oil within Taiwanese international commercial ports | 2018/08/31 | TSD |
| 1162 | Introduction to the Outcomes of MSC 99 | 2018/08/24 | XAD |
| 1159 | Adding Note on Survey Status to ships which is subject to Data collection system for fuel oil consumption of ships (IMO DCS) | 2018/08/09 | SMD |
| 1158 | Crack Damage on Cylinder Cover Cooling Jacket of Diesel Engine used as main propulsion | 2018/07/20 | RI |
| 1156 | Introduction to the outcomes of MEPC 72 | 2018/07/19 | XAD |
| 1155 | Instructions by the Administration of Germany regarding Guidance on Providing Safe Working Conditions for Securing of Containers on Deck (CSS Code Annex 14) | 2018/06/15 | HLD |
| 1152 | Exemption of fire extinguisher in boiler spaces | 2018/05/18 | EQD |
| 1151 | Added the matter, Security Information of Ships for which come from foreign ports and intended to enter ports in Japanese water | 2018/05/11 | SMD |
| 1148 | Guidance for vessels with inoperable ballast water management systems bound for US ports | 2018/04/03 | MCD |

| | | | |
|------|---|------------|-----|
| 1147 | Application of the code on noise levels on board ships below 1,600 GT for Singapore flagged ships | 2018/03/08 | MCD |
| 1146 | Electronic certificate service "ClassNK e-Certificate" | 2018/03/05 | CLD |
| 1145 | Amendment to the ClassNK Rules and Guidance related to computer based systems | 2018/02/28 | MCD |
| 1143 | Application of IMSBC Code 4th amendment | 2017/12/22 | EQD |
| 1142 | Amendment and on shipboard verification of DMLC(Part I and Part II) relating to the entry into force of the 2014 Amendments to the MLC,2006 | 2017/12/21 | SMD |
| 1141 | ----- No English version ----- | 2017/12/21 | SMD |
| 1140 | Voluntary Experience Building Phase of the IMO Data Collection System for fuel oil consumption for Singapore flagged ships | 2017/12/15 | SMD |
| 1139 | Data collection system for fuel oil consumption of ships (IMO DCS) required by the amendments to Annex VI of MARPOL 73/78 | 2017/12/15 | SMD |
| 1138 | Expansion of applicable ports subject to regulations on the sulphur content of fuel oil within Chinese emission control areas starting on 1 January 2018 | 2017/12/08 | MCD |
| 1137 | The Ship Security Alert System (SSAS) Test for the Panamanian Flagged Vessels | 2017/11/28 | SMD |
| 1136 | Periodical Survey in advance of Survey Window | 2017/11/21 | CLD |
| 1135 | Requirements of MARPOL ANNEX V amended by MEPC.277(70) | 2017/10/20 | MCD |
| 1134 | Issuance of Full-term certificate under ISM/ISPS Code at service sites | 2017/10/12 | SMD |
| 1133 | Introduction to the outcomes of MEPC 71 | 2017/10/05 | XAD |
| 1132 | Issuance of Full-Term Certificate of Classification, Certificate of Installations Registration and Statutory Certificates at service sites | 2017/09/22 | CLD |
| 1131 | Ballast Water Management method when operating in the waters of the United States | 2017/09/14 | MCD |
| 1130 | Regulations on the sulphur content of fuel oil within the Yangtze River Delta emission control area implemented from 1 September 2017 | 2017/09/12 | MCD |
| 1129 | Implementation of Electronic Chart Display and Information System (ECDIS) | 2017/09/11 | EQD |
| 1128 | ClassNK Guidelines on the Installation of Ballast Water Treatment Systems and Class Notation "BWTS" | 2017/09/08 | EQD |
| 1127 | Introduction to the Outcomes of MSC 98 | 2017/09/01 | XAD |
| 1126 | Record requirements of operational compliance with NOx Tier III regulation in Emission Control Areas | 2017/08/30 | MCD |
| 1125 | Re-coupling the decoupled IOPP (International Oil Pollution Prevention) Certificate Renewal Survey | 2017/08/28 | XAD |
| 1124 | Information regarding interim regulations within the Xiamen port area | 2017/08/24 | MCD |
| 1123 | Recognition and updated information of Company Security Officer for Panama Flagged ships | 2017/08/22 | SMD |
| 1120 | Preparation of IHM to be retained onboard the ship according to the EU Regulation on Ship Recycling, and the promotional incentives for examination fee to encourage earlier development of IHM | 2017/08/02 | SMD |
| 1117 | Guidelines related to the Paris Memorandum of Understanding (Paris MOU) for St. Vincent and the Grenadines flag vessels | 2017/07/20 | SVD |
| 1116 | Extension for the implementation deadline for Ballast Water Management System and Initial survey for the Ballast Water Management Convention | 2017/07/10 | MCD |
| 1113 | Initial survey for the Ballast Water Management Convention (Reminder) | 2017/06/15 | MCD |
| 1112 | "Launching at 5 knots" test of Lifeboat and Rescue boats for vessels under Netherlands flag | 2017/06/07 | SVD |
| 1111 | Updates of the EU regulation on monitoring, reporting and verification of carbon dioxide (CO2) emissions (EU MRV) | 2017/06/01 | QPD |
| 1110 | Guidance on application of CSS Code Annex 14 for Panamanian containerships | 2017/05/11 | HLD |
| 1109 | Treatment for Ballast Water Management Convention for Liberia flagged ships | 2017/05/02 | MCD |
| 1107 | Additional Ballast Water Management System Extension Program Update regarding USCG ballast water management | 2017/03/29 | MCD |
| 1106 | Revised IHO standards of Electronic Navigation Charts (ENC) using in Electronic Chart Display and Information System (ECDIS) - Japanese flag ships | 2017/03/22 | EQD |

| | | | |
|------|---|------------|-----|
| 1105 | Introduction to the Outcomes of MSC 97 | 2017/03/21 | XAD |
| 1103 | Introduction to the outcomes of MEPC 70 | 2017/03/10 | XAD |
| 1102 | Policy change - handling of ship security alert system transmissions for Marshall Islands flagged ships | 2017/02/28 | SMD |
| 1101 | Revised IHO standards of Electronic Navigation Charts (ENC) using in Electronic Chart Display and Information System (ECDIS) | 2017/02/17 | EQD |
| 1100 | Updates of the EU regulation on monitoring, reporting and verification of carbon dioxide (CO2) emissions (EU MRV) | 2017/01/31 | QPD |
| 1099 | Ballast Water Management System Extension Program Update regarding USCG ballast water management | 2017/01/10 | MCD |
| 1098 | Inspection and certification relating to the entry into force of the 2014 Amendments to the MLC,2006 on 18th January 2017 | 2016/12/28 | SMD |
| 1097 | Instructions by the Administration of Panama regarding Guidance on Providing Safe Working Conditions for Securing of Containers on Deck(CSS Code Annex 14) | 2016/12/28 | HLD |
| 1096 | An entry-into-force of an international code for ships operating in polar waters (POLAR Code) | 2016/12/27 | HLD |
| 1095 | Application of the additional requirements for relevant equipment of fire-fighter's outfit | 2016/12/26 | EQD |
| 1094 | De-harmonization of the IOPP (International Oil Pollution Prevention) Certificate Renewal Survey | 2016/12/16 | XAD |
| 1093 | The products covered by EU RO Mutual Recognition as fifth phase | 2016/12/14 | MCD |
| 1092 | Format Revision of Condition Evaluation Report (CER) | 2016/11/17 | CLD |
| 1091 | Instruction by the Administration of Marshall Islands regarding quantity of reserve cargo securing devices | 2016/11/16 | HLD |
| 1090 | Introduction to the Outcomes of MSC 96 | 2016/09/27 | XAD |
| 1088 | Additional information regarding regulations on the sulphur content of fuel oil within Chinese emission control areas - Implementation of regulations in the Port of Shenzhen | 2016/09/16 | MCD |
| 1087 | Amendment of Rules for windows located higher than the third tier above the freeboard deck and forward of the midship | 2016/09/14 | HLD |
| 1086 | Initial survey for the Ballast Water Management Convention after satisfaction the requirements for entry into force of the Convention | 2016/09/08 | MCD |
| 1085 | An entry-into-force of the International Convention for the Control and Management of Ships' Ballast Water and Sediments (BWM Convention) | 2016/09/08 | XAD |
| 1084 | Amendment to treatment for issuance of a short term ISSC on the completion of initial ISPS audit for Panama flagged ships | 2016/09/08 | SMD |
| 1083 | Instructions by the Administration of Liberia regarding Guidance on Providing Safe Working Conditions for Securing of Containers on Deck (CSS Code Annex 14) | 2016/08/31 | HLD |
| 1080 | Regulation 12 of Annex I MARPOL Amended requirements for sludge discharging piping and bilge-water piping | 2016/08/02 | MCD |
| 1078 | Introduction to the outcomes of MEPC 69 | 2016/07/22 | XAD |
| 1076 | Additional requirements of MARPOL ANNEX V amended by Polar code (MEPC.265(68)) | 2016/07/08 | MCD |
| 1075 | International Energy Efficiency (IEE) Certificate for Malaysian flagged vessels | 2016/07/06 | SMD |
| 1074 | Atmosphere Testing Instrument for Enclosed Spaces | 2016/06/30 | SVD |
| 1073 | IACS Procedural Requirement No.38 (Rev.1) in relation to Energy Efficiency Design Index (EEDI) | 2016/06/22 | HLD |
| 1069 | Requirements on Carriage of Nautical Publications on board for Marshall Islands flag ships | 2016/05/24 | EQD |
| 1068 | Regulations on the sulphur content of fuel oil within the Yangtze River Delta emission control area implemented on or after 1 April 2016 | 2016/05/02 | MCD |
| 1067 | "Guidance on ECDIS for ships calling at Australian ports" (revised) issued by AMSA | 2016/04/28 | SMD |
| 1066 | Effective scheduled date applicable to amended ClassNK Rules and Guidance related to tests of diesel engines | 2016/04/11 | MCD |
| | Instructions by the Administration of the United Kingdom (UK) regarding | | |

| | | | |
|------|---|------------|-----|
| 1065 | Guidance on Providing Safe Working Conditions for Securing of Containers on Deck | 2016/04/08 | HLD |
| 1063 | Additional information regarding regulations on the sulphur content of fuel oil within Chinese emission control areas | 2016/03/18 | MCD |
| 1061 | Additional requirements of portable gas detectors for existing vehicle carriers carrying motor vehicles with compressed hydrogen or natural gas in their tanks as fuel | 2015/12/28 | EQD |
| 1060 | Regulations on sulphur content of fuel oil within Chinese emission control areas | 2015/12/22 | MCD |
| 1059 | Instructions by the Administration of Singapore regarding Guidance on Providing Safe Working Conditions for Securing of Containers on Deck(CSS Code Annex 14) | 2015/12/09 | HLD |
| 1058 | Change of ships which are categorized as "Bulk carrier" on Safety Construction (SC) Certificate(s) and Safety Equipment (SE) Certificate(s) because of the clarification of term "Bulk carrier" | 2015/12/07 | CLD |
| 1057 | Application of IMSBC Code (2015 Edition) | 2015/12/03 | EQD |
| 1056 | Policy Letter for extension of implementation schedule for approved ballast water management methods (Revision 2) required according to USCG requirements | 2015/12/02 | MCD |
| 1055 | Additional information regarding USCG ballast water management regulation | 2015/11/12 | MCD |
| 1054 | Introduction to the Outcomes of MSC 95 | 2015/11/11 | XAD |
| 1053 | Mandatory installation of stability instrument for oil tankers, chemical tankers, gas carriers | 2015/11/02 | hLD |
| 1052 | Special requirements for Emergency Escape Breathing Devices(EEBDs) regarding Bahamas flagged vessels | 2015/10/29 | EQD |
| 1051 | Replacement from Statement of fact to Statement of Compliance for Inventory of Hazardous Materials onboard the vessel | 2015/10/27 | SMD |
| 1050 | Amendment of IMO's Guidelines for the development of the Inventory of Hazardous Materials regarding Ship Recycling Convention | 2015/10/27 | SMD |
| 1049 | Application method and additional information of extension of implementation of USCG ballast water management regulation | 2015/10/15 | MCD |
| 1048 | Survey and Certification for EEDI and SEEMP required by the Amendments to ANNEX VI of MARPOL 73/78 | 2015/10/05 | HLD |
| 1047 | Fuel sampling for ships calling in Member States of European Union (EU) | 2015/09/15 | MCD |
| 1045 | Equipment for the Singapore flag vessels | 2015/08/28 | EQD |
| 1044 | Change in email address for Ship Security Alert System for Singapore flagged ship | 2015/08/28 | SMD |
| 1043 | Introduction to the outcomes of MEPC 68 | 2015/08/27 | XAD |
| 1042 | Application of the Resolution MSC.277(85) relating to clarification of the term "Bulk Carrier" for Bermuda, British Virgin Islands, Cayman Islands, and Gibraltar flagged ships | 2015/08/06 | CLD |
| 1039 | Minimum propulsion power requirements to maintain the manoeuvrability of ships in adverse conditions (EEDI related requirements) | 2015/07/31 | HLD |
| 1037 | Medical Oxygen Cylinder onboard Tuvalu flagged Ships | 2015/07/31 | EQD |
| 1036 | The products covered by EU RO Mutual Recognition as fourth phase | 2015/07/31 | MCD |
| 1035 | Medical Oxygen Cylinder onboard Marshall Islands flagged vessels | 2015/07/01 | EQD |
| 1034 | Fuel regulations at berth in Hong Kong | 2015/06/24 | MCD |
| 1033 | STS Operations Plan for Marshall Islands Flag Ships | 2015/06/10 | HLD |
| 1032 | Atmosphere Testing Instrument for Enclosed Spaces(Singapore and Vanuatu) | 2015/06/02 | SVD |
| 1031 | Introduction to the EU regulation on monitoring, reporting and verification of carbon dioxide (CO2) emissions (EU MRV) | 2015/06/02 | XAD |
| 1030 | Preparation, conduct and analysis method of speed trial for EEDI verification | 2015/05/29 | HLD |
| 1029 | Treatment of bulkheads or decks having airborne sound insulation properties within accommodation spaces | 2015/05/29 | EQD |
| 1028 | Application of "Approved Method" to existing diesel engines under the provisions of MARPOL ANNEX VI -Addition of Approved Method for MAN B&W L50MC engines - | 2015/05/29 | MCD |
| 1027 | Special requirements for means of recharging breathing apparatus cylinders and spare cylinders regarding UK, Bermuda, British Virgin Islands, Cayman Islands, | 2015/05/22 | EQD |

| | | | |
|------|--|------------|-----|
| | Gibraltar and the Isle of Man flagged vessels | | |
| 1025 | Certificate of Proficiency for the security awareness training or security training for seafarers with designated security duties required under the provisions of STCW VI/6 | 2015/03/19 | SMD |
| 1024 | Introduction to the Outcomes of MSC94 | 2015/03/09 | XAD |
| 1023 | Special requirements for asbestos regarding St. Vincent and the Grenadines flagged vessels | 2015/02/26 | SVD |
| 1022 | Change in e-mail address for Ship Security Alert System (Japanese Flag Ship only) | 2015/02/19 | SMD |
| 1021 | Instructions by the Administration of St. Vincent and the Grenadines regarding Guidance on Providing Safe Working Conditions for Securing of Containers on Deck(CSS Code Annex 14) | 2015/02/17 | HLD |
| 1020 | Special requirements for means of recharging breathing apparatus cylinders and spare cylinders regarding St. Vincent and the Grenadines flagged vessels | 2015/01/23 | EQD |
| 1019 | Paris MoU Guidelines on Application of MARPOL Annex VI Reg.18 in an Emission Control Area (ECA) | 2014/12/26 | SMD |
| 1018 | Introduction to the Outcomes of MEPC 67 | 2014/12/26 | XAD |
| 1016 | Spare Charges, Additional Fire Extinguishers and Refilling of Extinguishers onboard the Panama flag ships | 2014/12/26 | EQD |
| 1015 | Application of the Resolution MSC.277(85) relating to clarification of the term "Bulk Carrier", and the instruction from the Isle of Man Government on this matter | 2014/12/19 | XAD |
| 1013 | Carriage of radioactive substances on cargo ships flying Bahamas Flag | 2014/11/19 | EQD |
| 1012 | Application of the Resolution MSC.277(85) relating to clarification of the term "Bulk Carrier", and the instruction from the Bahamas Government on this matter | 2014/11/14 | XAD |
| 1011 | Special requirements for relevant equipment of fire-fighter's outfit regarding Antigua and Barbuda flagged vessels | 2014/11/05 | EQD |
| 1009 | Special requirements for means of recharging breathing apparatus cylinders and spare cylinders regarding Singapore flagged ships | 2014/10/21 | EQD |
| 1008 | Special requirements for means of recharging breathing apparatus cylinders and spare cylinders regarding Bahamas flagged vessels | 2014/10/10 | EQD |
| 1005 | Change of addressee and Form for Declaration of Company Security Officer (CSO) under the Panama Maritime Authority | 2014/09/11 | SMD |
| 1003 | Test standards, etc. established in IMSBC Code on cargo ships flying UK (MCA) Flag | 2014/08/28 | EQD |
| 1001 | Introduction to the Outcomes of MSC93 | 2014/08/19 | XAD |
| 999 | Instructions by the administration of Cyprus regarding Guidance on providing Safe Working Conditions for Securing Containers on Deck (CSS Code Annex 14) | 2014/08/13 | HLD |
| 996 | Guidelines for preparation of cargo securing manuals | 2014/08/01 | HLD |
| 993 | The products covered by EURO Mutual Recognition as third phase | 2014/07/29 | MCD |
| 992 | ClassNK "NOTATION HANDBOOK" now available on the ClassNK website. | 2014/07/02 | CLD |
| 991 | Introduction to the Outcomes of MEPC 66 | 2014/06/26 | XAD |
| 989 | Protection against noise in machinery space on board the Hong Kong flag ships | 2014/06/20 | MCD |
| 987 | Carriage and testing of IRON ORE FINES on cargo ships flying Antigua and Barbuda Flag | 2014/06/10 | EQD |
| 986 | Frequently Asked Questions (FAQs) regarding the Use of Environmentally Acceptable Lubricants (EAL)(in association with the U.S. Environmental Protection Agency's 2013 VGP) | 2014/05/26 | MCD |
| 985 | Plans and procedures for recovery of persons from the water (Related to SOLAS III) | 2014/05/23 | SVD |
| 984 | Helicopter facilities onboard ships sailing in Australian waters | 2014/04/08 | SVD |
| 983 | Regarding amendments of IBC Code which will enter into force from 1 June 2014 | 2014/03/14 | HLD |
| 982 | Survey on lifeboat on-load release mechanisms (Lifeboat Release and Retrieval Systems: LRRSs) for ships flying Bahamian flag | 2014/02/06 | EQD |
| 981 | Additional information for "Final 2013 Vessel General Permit issued by US Environmental Protection agency" | 2014/01/29 | MCD |
| 978 | Introduction to the EU Regulation on Ship Recycling | 2014/01/15 | SMD |
| | Addition of a new "Type of Ship" display function (for use with certain statutory | | |

| | | | |
|-----|--|------------|-----|
| 976 | certificates) to the Ship Status Search Service "NK-SHIPS" | 2013/12/02 | CLD |
| 975 | Carriage requirements for Bridge Navigational Watch Alarm System (BNWAS) (Excluding Japanese-flagged ships) | 2013/11/29 | EQD |
| 974 | Special requirements for Life-saving appliances and Equipment onboard Panamanian flagged vessels | 2013/11/20 | EQD |
| 973 | Surveys of new building ships on implementation of MLC, 2006 | 2013/11/15 | SMD |
| 972 | Non-Tank Vessel Response Plan (NTRVP) Final Rule issued by USCG | 2013/11/08 | MCD |
| 971 | Extension of implementation schedule for vessels subject to ballast water management (BWM) discharge standards of USCG | 2013/11/08 | MCD |
| 969 | Adoption of IACS UI SC262 | 2013/10/21 | XAD |
| 968 | "Final 2013 Vessel General Permit issued by US Environmental Protection Agency" | 2013/10/18 | MCD |
| 966 | Survey on lifeboat on-load release mechanisms (Lifeboat Release and Retrieval Systems: LRRSs) | 2013/10/03 | EQD |
| 965 | Summary of the outcomes of MSC92 | 2013/09/30 | XAD |
| 964 | Information of "VESSEL REQUIREMENTS FOR NEW PANAMAX" from Panama Canal Authority | 2013/09/03 | HLD |
| 962 | The products covered by EU RO Mutual Recognition as second phase | 2013/07/26 | MCD |
| 961 | Adoption of IACS UI SC191 (Rev.5) | 2013/07/25 | XAD |
| 959 | Change of the definition of "Bulk Carrier" on SC / SE / SF Certificates (for the vessels which keel was laid on or after 1st July 2006) | 2013/07/22 | CLD |
| 958 | Introduction to the Outcomes of MEPC65 | 2013/07/18 | XAD |
| 957 | Symbols of Fire Control Plans for Panamanian flagged vessels | 2013/07/16 | EQD |
| 951 | Alternate Management Systems based on USCG "Standards for Living Organisms in Ship's Ballast Water Discharged in U.S. Waters" (Obligation of installation of ballast water management system for the vessels engaged in U.S. waters) | 2013/05/09 | MCD |
| 950 | Omission of "Launching at 5 knots" test of Rescue boat(s) for Malta flagged vessels | 2013/04/18 | SVD |
| 949 | ----- No English version ----- | 2013/04/15 | CLD |
| 948 | Servicing of Inflatable Liferaft on board Malta-registered Ships | 2013/04/08 | SVD |
| 947 | Summary of the outcomes of MSC91 | 2013/04/02 | XAD |
| 946 | EU Mutual Recognition for products for marine use in accordance with Article 10 of REGULATION (EC) No 391/2009 | 2013/03/29 | MCD |
| 945 | "Evaluating a Vessel's Ballast Water Management Plan" published by USCG and introduction of Fouling and Sediment Management | 2013/03/01 | MCD |
| 944 | Introduction to the Outcomes of MEPC 64 | 2013/02/15 | XAD |
| 943 | Performance standard for navigation lights - Japanese flag ships | 2013/02/05 | EQD |
| 942 | ----- No English version ----- | 2013/02/04 | CLD |
| 941 | Amendments to the Guidance related to the Application of Planned Machinery Surveys (CMS, PMS) | 2013/01/18 | SVD |
| 940 | Safety Radio (SR) survey of Japanese flag ships on or after 1 January 2013 | 2012/12/25 | EQD |
| 937 | Special requirements for Life-saving appliances and Equipment onboard Panamanian flagged vessels | 2012/12/17 | EQD |
| 934 | Special requirements for Life-saving appliances and Equipment onboard Hong Kong flagged vessels | 2012/12/03 | EQD |
| 932 | Appraisal service according to the revised MARPOL ANNEX V | 2012/11/30 | MCD |
| 930 | ----- No English version ----- | 2012/10/31 | SMD |
| 928 | Port State Control (PSC) within North American Emission Control Area (ECA) under MARPOL ANNEX VI by U.S. Coast Guard/Environmental Protection Agency (EPA) and Canada | 2012/10/01 | SMD |
| 927 | Summary of LSA Code amendments adopted by Marine Safety Committee (MSC) at the 87th session Rev.1 | 2012/09/14 | EQD |
| 926 | Summary of the outcomes of MSC90 | 2012/09/14 | XAD |
| 925 | New instruction for Unified Interpretation regarding the suction heads of fixed | 2012/09/03 | XAD |

| | | | |
|-----|--|------------|-----|
| | emergency fire pumps from Vanuatu flag | | |
| 921 | Maintenance, servicing and inspection for lifeboats and launching appliances | 2012/08/16 | SMD |
| 918 | Indication of the character "M0" on "Certificate of Classification" for ships flying a flag other than Japanese with the installations registration of "Automatic and Remote Control Systems" | 2012/07/31 | CLD |
| 916 | Commencement of control for SOx and particulate matter (PM) within North American Emission Control Area under MARPOL ANNEX VI. | 2012/07/24 | MCD |
| 915 | Each flag state's reply/instruction for Unified Interpretation regarding the suction heads of fixed emergency fire pumps | 2012/07/20 | XAD |
| 914 | Introduction to the Outcomes of MEPC63 | 2012/07/20 | XAD |
| 912 | Treatment of ECDIS not displaying radar video | 2012/07/03 | EQD |
| 911 | Annual Test of Automatic Identification System (AIS) | 2012/06/28 | EQD |
| 909 | Each flag state's reply/instruction for Unified Interpretation regarding the suction heads of fixed emergency fire pumps | 2012/06/25 | XAD |
| 908 | Verification for the Material and Equipment not containing asbestos | 2012/06/22 | SVD |
| 906 | The devices to prevent the passage of flame into cargo tanks in chemical and oil/chemical tankers | 2012/06/13 | EQD |
| 903 | USCG "Standards for Living Organisms in Ship's Ballast Water Discharged in U.S. Waters"(Obligation of installation of ballast water management system for the vessels engaged in U.S. Waters) and New York State Ballast Water Standards | 2012/05/08 | MCD |
| 902 | Emission Control of Volatile Organic Compounds (VOCs) from tankers - Designated Ports in Netherlands and the Republic of Korea | 2012/04/13 | HLD |
| 900 | Fire Protection Systems and Appliances for the Marshall Islands flag vessels | 2012/04/03 | EQD |
| 898 | Steel coil loading program of existing dry cargo ships to which Common Structural Rules is applied | 2012/03/23 | HLD |
| 897 | For Singapore Ships, MPA Instruction to prevent PSC detention | 2012/03/14 | SMD |
| 895 | Maintenance, inspection and test of Fixed Dry Chemical Powder Fire-Extinguishing Systems and Appliances on board the Marshall Islands flagged ships | 2012/03/09 | SVD |
| 894 | Information of the lifeboat release and retrieval systems from Cyprus Government | 2012/03/06 | EQD |
| 893 | Fall Preventer Devices (FPDs) for the Norwegian Flagged vessels | 2012/02/21 | EQD |
| 892 | New instruction for the additional liferaft from Liberian Flag | 2012/02/21 | EQD |
| 891 | New instruction for Unified Interpretation regarding the suction heads of fixed emergency fire pumps from Marshall Islands Flag | 2012/02/13 | XAD |
| 890 | New instruction for Unified Interpretation regarding the suction heads of fixed emergency fire pumps from Liberian Flag | 2012/02/10 | XAD |
| 889 | Notice of Carriage of the solid bulk cargoes which is not listed in IMSBC Code from the Singapore Government | 2012/02/09 | EQD |
| 888 | Special requirements for Life-saving appliances and Equipment onboard Marshall Islands flagged vessels | 2012/01/20 | EQD |
| 887 | New instruction for Unified Interpretation regarding the suction heads of fixed emergency fire pumps from Singapore, Belgium and Red Ensign Group Technical Forum (including the UK, Bermuda, British Virgin Islands, Cayman Islands, Gibraltar, the Isle of Man | 2012/01/06 | XAD |
| 886 | Fall Preventer Devices (FPDs) for the Hong Kong-registered vessels | 2011/12/26 | EQD |
| 884 | Confirmation of Periodical Surveys for Emergency Fire Pumps | 2011/12/13 | SVD |
| 883 | Recent development of PSC Inspection related to ISM Code | 2011/12/13 | SMD |
| 882 | Fuel Sulphur Regulations in Turkish Ports, Inland Waterways and Territorial Waters | 2011/12/08 | MCD |
| 880 | Ballast Water Management Plans for vessels flying Malaysian Flag | 2011/11/29 | MCD |
| 879 | Fuel Oil Controls by the State of California, USA | 2011/11/29 | MCD |
| 878 | Application of "Approved Method" to existing diesel engines under the provisions of MARPOL ANNEX VI - Certification of an Approved Method for MAN B&W S60MC engines - | 2011/11/25 | MCD |
| 877 | Requirements for sulphur content of fuel oil implemented on and after 1 January 2012 | 2011/11/25 | MCD |

| | | | |
|-----|---|------------|-----|
| 875 | The Mediterranean Sea - Requirement for Ballast Water Management | 2011/11/24 | MCD |
| 873 | Load Line Mark for Vietnamese flagged vessel | 2011/11/11 | HLD |
| 872 | Introduction of the outcomes of MEPC62 | 2011/11/10 | XAD |
| 871 | Enhanced Monitoring Programme for Bahamas-registered ships | 2011/11/10 | SVD |
| 870 | Change on the Renewal method of Safety Management Certificate (SMC) and International Ship Security Certificate (ISSC) (except Japanese flag vessels) | 2011/11/08 | SMD |
| 867 | Application of "Approved Method" to existing diesel engines under the provisions of MARPOL ANNEX VI - Certification of an Approved Method for MAN B&W S70MC and S50MC engines - | 2011/10/07 | MCD |
| 866 | Designation of United States Caribbean Emission Control Area under MARPOL ANNEX VI (Regulations for the Prevention of Air Pollution from Ships) | 2011/10/04 | MCD |
| 865 | Information for Boat Davit Limit Switches from the UK Government and Marshall Islands Government | 2011/09/28 | EQD |
| 864 | Maintenance, inspection and test of Fire-Protection Systems and Appliances on board the Bahamas-registered ships | 2011/09/21 | SVD |
| 863 | Appraisal services for energy efficiency improvement of ships | 2011/08/30 | HLD |
| 862 | Fall Preventer Devices (FPDs) for the Maltese Flagged vessels | 2011/08/18 | EQD |
| 861 | New instruction for Unified Interpretation regarding the suction heads of fixed emergency fire pumps from Maltese flag | 2011/08/11 | XAD |
| 860 | Each flag state's reply/instruction for Unified Interpretation regarding the suction heads of fixed emergency fire pumps | 2011/08/08 | XAD |
| 858 | Introduction of the outcomes of MSC89 | 2011/08/01 | XAD |
| 857 | ----- No English version ----- | 2011/06/21 | EQD |
| 856 | Lifeboats and Liferrafts pharmacies for vessels flying the Greek Flag | 2011/06/15 | EQD |
| 854 | New Guideline related to the Paris Memorandum of Understanding (Paris MOU) for Panamanian Ships of 20 years of age or more | 2011/05/19 | SVD |
| 853 | Replacement of IAPP Certificate due to change in procedure for completing Supplement | 2011/05/19 | MCD |
| 852 | Guideline for measurement of dose rate for ships in Japanese ports | 2011/04/28 | SVD |
| 851 | Latest development of PSC Inspection related to PSC Deficiency Code 1560 "Charts" and 1594 "Voyage or passage plan" | 2011/04/07 | SMD |
| 850 | ----- No English version ----- | 2011/03/18 | SVD |
| 849 | Special requirements for Life-saving appliances and Equipment on board Isle of Man Flagged vessels | 2011/03/10 | EQD |
| 848 | Application of "Approved Method" to existing diesel engines under the provisions of Revised MARPOL ANNEX VI - Certification of an Approved Method for WARTSILA RTA engines - | 2011/03/07 | MCD |
| 847 | Provision and Display of Manoeuvring Information on board Liberian Flag Ships - Revised - | 2011/03/07 | EQD |
| 846 | ----- No English version ----- | 2011/02/28 | MCD |
| 845 | Carriage of cargoes which may liquefy | 2011/02/24 | HLD |
| 844 | Prohibition of carriage and use as fuel of heavy grade oils in the Antarctic area (MARPOL Annex I Reg.43) | 2011/02/24 | MCD |
| 843 | ----- No English version ----- | 2011/02/18 | MCD |
| 842 | USCG Marine Safety Alert (Inspection of Fuel Oil Quick -Closing Valves) | 2011/02/10 | SVD |
| 841 | Panamanian flagged ships carrying Solid Bulk Cargoes other than Grain | 2011/02/09 | EQD |
| 840 | ----- No English version ----- | 2011/01/14 | HLD |
| 839 | Amendment of requirement to different classes of dangerous goods except solid dangerous goods in bulk in regulation II-2/19 of SOLAS 1974 | 2010/12/20 | EQD |
| 837 | The remotely located survival craft (liferaft required by SOLAS Chapter III/31.1.4) flying Isle of Man Flag | 2010/12/06 | EQD |
| 836 | "Approved Method" applied to existing diesel engines under provisions of Revised MARPOL ANNEX VI - Certification of an Approved Method for MAN B&W S70MC - | 2010/12/01 | MCD |
| 835 | Procedure of PSC exam for Banning of Foreign vessels by USCG | 2010/11/30 | SVD |
| | STS Operations Plan required by Amendments to MARPOL Annex I (Regulation | | |

| | | | |
|-----|---|------------|-----|
| 834 | for the prevention of pollution by oil) (For non-Japanese flag ships) | 2010/11/22 | HLD |
| 833 | Information for Life-saving appliances (Lifebuoy, Thermal Protective Aid) from the U.K. Government | 2010/11/18 | EQD |
| 832 | Designation of North American Emission Control Area under MARPOL ANNEX VI (Regulations for the Prevention of Air Pollution from Ships) | 2010/11/11 | MCD |
| 831 | Annex I of MARPOL 73/78 Oil residue (sludge) service tank listed in the Supplement to IOPP Certificate and new form of the Supplement | 2010/11/05 | MCD |
| 830 | Voyage Repairs and Maintenance | 2010/10/20 | SVD |
| 828 | Special Requirements of Panama Maritime Authority, Bahamas Maritime Authority and Marshall Islands Government in relation to Revisions of the ISM Code on 1 July 2010 | 2010/09/15 | SMD |
| 827 | Requirement of Infant and Oversize adult lifejackets as amended by MSC.201 (81) - U.K. registered ships | 2010/08/30 | EQD |
| 825 | The New Inspection Regime (NIR) of Paris MOU | 2010/08/12 | SVD |
| 821 | 2008 IS Code | 2010/07/27 | HLD |
| 820 | Approved Companies for Shore-based Maintenance of GMDSS Radio Installations and for Inspection of Satellite EPIRBs on board the Greek Flag Ships | 2010/07/20 | EQD |
| 819 | Technical appraisal service of ship performance in actual seas "10 Mode Performance Index for Ships" | 2010/07/05 | TSD |
| 818 | Requirement of Infant and Oversize adult lifejackets as amended by MSC.201 (81) | 2010/06/30 | EQD |
| 817 | The new standard of Life-saving equipment by the amendments to LSA Code (enter into force on 1 July 2010) | 2010/06/30 | EQD |
| 816 | ----- No English version ----- | 2010/06/30 | MCD |
| 815 | Application of Tonnage Certificate (ITC'69) endorsements for Panamanian Flagged Vessels | 2010/06/17 | CLD |
| 814 | New York State Ballast Water Standards | 2010/06/14 | EQD |
| 812 | ----- No English version ----- | 2010/05/20 | HLD |
| 811 | Emergency Towing Booklet | 2010/05/14 | SVD |
| 810 | Amendments to MARPOL Annex VI (Regulation for the prevention of air pollution from ships) which comes to effect from 1st July 2010 for non-Japanese flag ships | 2010/04/20 | MCD |
| 807 | Other means of embarkation for remotely located survival crafts flying Panama Flag / Rev. 1 | 2010/03/30 | EQD |
| 805 | Remotely located survival craft (SOLAS Chapter III/31.1.4) - U.K. registered ships | 2010/02/15 | EQD |
| 804 | Radio Service Publications, Radio Log-Book and Radio Personnel on board Australian registered GMDSS ships | 2010/02/15 | EQD |
| 803 | Remotely located survival craft(III/31.1.4) - Australian registered ships | 2010/02/10 | EQD |
| 802 | Special requirements for Life-saving appliances and Equipment onboard Marshall Islands flagged vessels- The guidance for the survey matters - | 2010/01/27 | EQD |
| 801 | Entry into force of the Resolution MSC.273(85) relating to amendments to the International Management Code for the safe operation of ships and for pollution prevention (International Safety Management (ISM) Code) | 2010/01/26 | SMD |
| 799 | Pressure Test of Cylinders of High Pressure CO2 fire-extinguishing systems on board Denmark Flagged Vessels | 2010/01/15 | SVD |
| 798 | Steel coil loading program of existing dry cargo ships | 2010/01/07 | HLD |
| 797 | Use of low sulphur fuels under the EC Directive 2005/33/EC | 2009/12/28 | MCD |
| 796 | Special requirements for Life-saving appliances and Equipment onboard Marshall Islands flagged vessels | 2009/12/28 | EQD |
| 795 | Amendment to application forms "Application for Classification and Statutory Service During Construction", "Application for Surveys and Issue of Certificates" and "Application for Classification and Statutory Service for an Existing Ship", and establishment of application form "Application for Issue of Certificates" | 2009/12/24 | CLD |
| 794 | Controls for fixed carbon dioxide fire-extinguishing systems for ships constructed before 1 October 1994 | 2009/12/18 | EQD |
| 793 | Performance standard for navigation lights, navigation light controllers and associated equipment - Australian registered ships | 2009/12/10 | EQD |

| | | | |
|-----|--|------------|-----|
| 792 | Extension of statutory certificates and the period of servicing of liferafts for Panamanian flagged ships | 2009/12/01 | SVD |
| 791 | ROPME Sea Area - Requirement for Ballast Water Management | 2009/11/25 | MCD |
| 789 | Measures by ClassNK in response to "International Convention for the Control and Management of Ship's Ballast Water and Sediments" | 2009/11/12 | EQD |
| 788 | Amendments to requirements for crankcase oil mist detection arrangements | 2009/11/09 | MCD |
| 787 | ----- No English version ----- | 2009/10/30 | SMD |
| 786 | Stowage and segregation requirements of COAL and BROWN COAL BRIQUETTES | 2009/10/09 | EQD |
| 785 | Surveys and Certification for "Vessel General Permit" required by the U.S. Environmental Protection Agency | 2009/10/08 | SVD |
| 783 | Recording engine parameters as required for diesel engines in accordance with MARPOL Annex VI | 2009/08/24 | MCD |
| 781 | Inadvertent discharges of Fixed CO2 fire extinguishing systems - ANSUL CO2 cylinder valves | 2009/08/12 | EQD |
| 780 | Application of Council Directive 96/98/EC on marine equipment as amended by Commission Directive 2008/67/EC, to Cyprus flagged vessels | 2009/08/06 | EQD |
| 779 | ----- No English version ----- | 2009/07/31 | TSD |
| 778 | Embarkation arrangement for remotely located survival craft flying Cyprus Flag | 2009/07/31 | EQD |
| 777 | Radio Log Books on Marshall Islands Flag GMDSS ships | 2009/07/30 | EQD |
| 776 | Postponement of the implementation of IACS CSR for Double Hull Oil Tankers, July 2008 "Rule Change Notice No. 1" | 2009/07/14 | XAD |
| 775 | Cyprus flag ships carrying Solid Bulk Cargoes other than Grain | 2009/06/26 | EQD |
| 773 | Class Notation of "In water Survey" | 2009/05/25 | SVD |
| 771 | Beginning of NOx Appraisal Service in accordance with Amendments to MARPOL Annex VI and NOx Technical Code | 2009/05/13 | MCD |
| 770 | Affixation of the notation regarding environmental measures to ship classification characters and issuance of Environmental Guideline | 2009/05/01 | DMD |
| 769 | Application for Exemptions, Extensions and/or Equivalence to International Convention Requirements for Bahamian Flag Ships (Revision) | 2009/03/13 | SVD |
| 768 | The maintenance of falls used in launching appliances for Singapore flagged vessels | 2009/02/25 | EQD |
| 766 | MARPOL Annex IV / Application of Resolution MEPC.159(55) revised Guidelines on implementation of effluent standards and performance tests for sewage treatment plants | 2009/02/16 | MCD |
| 765 | Application of the Resolution MSC.277(85) relating to clarification of the term "Bulk Carrier" etc., and the instruction from the Bahamas Government on this | 2009/02/03 | XAD |
| 761 | Regarding the revised Japanese Government Regulations in accordance with IBC/BCH code & MARPOL 73/78 Annex II which comes to effect from 1 January 2009 (For Japanese flag ships) | 2008/12/22 | HLD |
| 760 | Performance standard for navigation lights, navigation light controllers and associated equipment - Singapore flagged vessels | 2008/12/22 | EQD |
| 758 | MARPOL Annex IV Approval of Discharge Rate of Untreated Sewage from Sewage Holding Tank | 2008/12/12 | MCD |
| 754 | Implementation of Long Range Identification and Tracking of Ships (LRIT) - 2 - | 2008/12/05 | EQD |
| 753 | Regarding the revised IBC/BCH code & MARPOL 73/78 Annex II which comes to effect from 1 January 2009 (For ships other than Japanese flag ships) | 2008/10/23 | HLD |
| 752 | Embarkation arrangement for remotely located survival craft flying Maltese Flag | 2008/10/23 | EQD |
| 751 | For ships flying Japanese flag, Correction of description on the certificate of fitness for ships carrying dangerous goods. (Prohibition of stowage of such Class 5.2 dangerous goods; "Organic Peroxides" under deck or in enclosed spaces) | 2008/10/10 | EQD |
| 750 | Implementation of Long Range Identification and Tracking of Ships (LRIT) | 2008/10/08 | EQD |
| 749 | Carriage of immersion suits for the additional liferaft on cargo ships flying Bahamas Flag | 2008/10/06 | EQD |
| 748 | Adoption of IACS CSR/BC RCP3 | 2008/09/25 | XAD |
| 745 | Surveys and Certification for AFS Convention | 2008/09/05 | SVD |
| 743 | International Convention on AFS enters into force on 17 September 2008 (Part 2) | 2008/08/15 | SVD |

| | | | |
|-----|--|------------|-----|
| 742 | UI SC213(Rev.1) for non-Japanese flag ships "A knotted rope is not acceptable for this Rev.1" | 2008/08/05 | EQD |
| 740 | Amendments to requirements for "Operational readiness, maintenance and inspection" of life-saving appliances in Reg.III/20 of SOLAS | 2008/06/27 | SVD |
| 738 | Embarkation arrangement for the remotely located survival craft on Singapore flagged ships | 2008/06/26 | EQD |
| 736 | The approval test of crankcase explosion relief valves (Replacement of ClassNK Technical Information No. TEC-0720) | 2008/06/06 | MCD |
| 734 | Notice from Panama Marine Authority | 2008/05/29 | EQD |
| 731 | Amendments to the Guidance on the Confirmatory Survey of Continuous Machinery Survey (CMS) | 2008/04/28 | SVD |
| 730 | Application for Service Extensions or Dispensations of life-savings/fire-fighting appliances and Extension of Statutory Certificates for Marshall Islands Flag Ships | 2008/04/15 | SVD |
| 729 | International Convention on AFS enters into force on 17 September 2008 | 2008/04/07 | SVD |
| 728 | New item "IACS Unified Requirement and Unified Interpretation" on ClassNK web-site | 2008/04/02 | XAD |
| 727 | Immersion suits for the additional life raft | 2008/04/01 | EQD |
| 725 | Annex IV of MARPOL 73/78 for existing ships | 2008/03/11 | MCD |
| 724 | Revised cargo gear regulation of Australia | 2008/01/22 | EQD |
| 723 | ----- No English version ----- | 2008/01/21 | MCD |
| 722 | Approvals of stability programme for oil, chemical and gas carriers flying UK flag | 2008/01/15 | HLD |
| 717 | Application of Harmonized System of Survey and Certification (HSSC) to Panamanian flag ships | 2007/11/19 | CLD |
| 716 | Periodic Inspection, Testing and Maintenance of Compressed Gas Cylinders, Fire Extinguishers and Fixed Fire-fighting System onboard the Isle of Man Flagged Vessels | 2007/11/07 | SVD |
| 715 | Emergency escape breathing devices (EEBDs) onboard the Vanuatu flagged vessels | 2007/11/01 | EQD |
| 713 | Abolishment of Special Requirements for INMARSAT-C Ship Earth Stations of Singapore Flag Ships | 2007/10/16 | EQD |
| 710 | An entry-into-force of the AFS Convention | 2007/09/26 | XAD |
| 707 | Introduction of the outcomes of MEPC56 | 2007/08/17 | XAD |
| 704 | Definition of date of "contract for construction"- Revision 4 of IACS Procedural Requirement No.29 | 2007/07/26 | XAD |
| 703 | Lifeboat Air Support Systems for Liberian Flag Ships | 2007/07/03 | SVD |
| 702 | Non-destructive tests for butt welding joint of extremely thick steel plates in large container ships | 2007/06/13 | SVD |
| 701 | Amendments to the Finnish-Swedish Ice Class Rules | 2007/06/08 | SVD |
| 700 | Annex IV of MARPOL 73/78 for existing Japanese-registered ships | 2007/06/08 | MCD |
| 698 | Summary of SOLAS Chapter III and LSA Code amendments adopted by Marine Safety Committee (MSC) at the 81st and 82nd session | 2007/05/23 | EQD |
| 696 | Servicing Intervals of Life-saving Appliances on board the Bahamas flagged vessels | 2007/05/15 | SVD |
| 694 | Regarding the release gear mechanism, type SRS-37 which is equipped on lifeboats manufactured by Shigi Shipbuilding Co., Ltd. | 2007/04/13 | EQD |
| 691 | Introduction of the outcomes of MSC 82 | 2007/02/22 | XAD |
| 690 | Ballast Water Management - Requirement introduced by State of Qatar | 2007/01/25 | MCD |
| 689 | Introduction of the IACS early implementation of IMO "Performance Standards for Protective Coatings for ballast tanks and void spaces" for ships subject to the CSRs | 2006/12/26 | XAD |
| 688 | Operation tests of the relieving gears of the safety valves provided on the boilers at the Periodical Surveys | 2006/12/22 | SVD |
| 687 | Fuel Oil Controls by the European Union and by the State of California, USA | 2006/12/14 | MCD |
| 686 | Construction Drawings to be maintained on Board the Ship and Ashore | 2006/12/13 | SMD |
| 685 | Survey Preparations for Bulk Carriers and Oil Tankers based on amended IMO Resolution A.744 (18). (Part 2) | 2006/12/13 | SVD |

| | | | |
|-----|--|------------|-----|
| 684 | IACS UI SC213 for non-Japanese flag ships | 2006/12/07 | EQD |
| 683 | Annex IV of MARPOL 73/78 for existing ships | 2006/11/20 | MCD |
| 682 | Introduction of the outcomes of IMO MEPC 55 | 2006/11/17 | XAD |
| 681 | Shipboard Oil Pollution Emergency Plan (Regulation 37.4 of Annex I to MARPOL Annex 73/78) Prompt Access to Shore-based Computer Programs | 2006/11/09 | MCD |
| 680 | ClassNK Emergency Technical Assistance Service (ETAS) | 2006/11/09 | SVD |
| 676 | Annual Thorough Examination of the Lifeboats and Launching Appliances | 2006/10/17 | SVD |
| 675 | Fire extinguishing systems onboard the Cayman Islands flagged vessels | 2006/10/13 | EQD |
| 671 | SMPEP for noxious liquid substances which the ships are newly required to keep onboard by the amendments to Annex II of MARPOL 73/78 | 2006/09/22 | MCD |
| 668 | Introduction of the outcomes of MSC 81 | 2006/07/12 | XAD |
| 665 | Survey Preparations for Bulk Carriers and Oil Tankers based on IMO Resolution A.744(18), as amended. | 2006/07/05 | SVD |
| 664 | S-VDR for Ships Constructed before 1 July 2002 and Shore-based Maintenance of Satellite EPIRBs (for Non-Japanese Ships) | 2006/06/23 | EQD |
| 663 | Triangular mark regarding the restrictions from sailing with any cargo hold empty for Bulk Carriers (Revised SOLAS, Chapter XII / Reg. 8 and 14) | 2006/06/22 | SVD |
| 662 | Ballast Water Management - Reporting Requirement introduced by US Washington State | 2006/06/22 | MCD |
| 661 | ----- No English version ----- | 2006/06/19 | EQD |
| 660 | Testing of Air Bottles for Lifeboats with Self-Contained Air Support System for Bahamanian Ships | 2006/05/29 | SVD |
| 659 | Survey and certificate for crew accommodation of vessels flying Belize Flag | 2006/05/09 | EQD |
| 657 | Introduction of the outcomes of MEPC 54 | 2006/04/27 | XAD |
| 656 | Maintenance, servicing and inspection for lifeboats and launching appliances | 2006/04/19 | SVD |
| 655 | Revised MARPOL 73/78 Annex II and IBC Code | 2006/04/19 | HLD |
| 654 | SOx Emission Control Areas specified in MARPOL 73/78 ANNEX VI (Regulations for the Prevention of Air Pollution from Ships) | 2006/04/13 | MCD |
| 653 | Expansion of Japanese flag ships subject to the ISPS Code application owing to the mandatory application of tonnage measurement as regulated by the TM 69 convention. | 2006/04/10 | SMD |
| 652 | Fire control plans onboard the Singapore flag ships | 2006/03/22 | EQD |
| 651 | Restrictions on sailing with any cargo hold empty for Bulk Carriers according to the Revised SOLAS, Chapter XII/Reg. 14 which comes into effect on 1 July 2006 and deletion of the concerned Class Notations (partial) or Descriptive Notes for Classification Character | 2006/03/20 | CLD |
| 649 | Marking of Freeboard Marks for Panamanian flagged ships | 2006/02/23 | SVD |
| 648 | Ballast Water Management Plan | 2006/02/14 | MCD |
| 647 | IACS CSR (Common Structural Rules) have been incorporated into the Society's Rules: | 2006/02/14 | HLD |
| 645 | Pressure/Vacuum(PV) Valves manufactured by TANKTECH Co. installed on board Maltese flagged ships | 2005/12/21 | SVD |
| 641 | Emergency Training and Drills - Launching of Lifeboats - for Cyprus Ships | 2005/11/09 | SMD |
| 640 | Maintenance of Shipboard Passenger Lifts (= Elevators for human use) installed on Hong Kong registered ships | 2005/10/05 | SMD |
| 638 | Introduction of the outcomes of MEPC 53 | 2005/09/14 | XAD |
| 637 | In-water survey of Bahamian passenger ships | 2005/08/31 | SVD |
| 636 | ----- No English version ----- | 2005/08/04 | MCD |
| 633 | Introduction of the outcomes of MSC 80 | 2005/07/13 | XAD |
| 632 | Restrictions on sailing with any cargo hold empty for Bulk Carriers (Revised SOLAS, Chapter XII / Reg. 14) | 2005/06/27 | SVD |
| 627 | Initial Survey for MARPOL 73/78 ANNEX VI (Regulations for the prevention of air pollution from ships) | 2005/04/20 | MCD |
| 626 | Implementation of the revised Regulation 13G and new Regulation 13H of MARPOL Annex I (Hong Kong and Singapore) | 2005/04/15 | XAD |

| | | | |
|-----|--|------------|-----|
| 622 | Introduction of the outcomes of MSC79 | 2005/03/10 | XAD |
| 621 | Periodic servicing of launching appliances for Cyprus flagged ships | 2005/03/04 | EQD |
| 620 | Annex VI of MARPOL 73/78 (Regulations for the prevention of air pollution from ships) | 2005/02/03 | MCD |
| 619 | Portable fire extinguishers and Fire control plans on board the Netherlands flagged ships | 2005/01/25 | EQD |
| 618 | EU amending regulation for CAS clarification and alignment with MARPOL | 2005/01/24 | SVD |
| 616 | Safekeeping of Audit record for Ship Security System | 2004/12/24 | SMD |
| 615 | Amendments to Rules for Cargo Handling Appliances | 2004/12/20 | EQD |
| 614 | Maintenance and renewal of wire falls used in launching for Bahamian flagged vessels | 2004/12/16 | SVD |
| 613 | IMO Resolution MEPC. 107(49)"Revised Guidelines and Specifications for Pollution Prevention Equipment for Machinery Space Bilges of Ships" | 2004/12/15 | MCD |
| 612 | For ships other than ships flying the Japanese flag, descriptions matter correction of certificate of fitness for ship carrying dangerous goods. | 2004/12/08 | EQD |
| 610 | Periodical Maintenance, Inspection and Testing of Portable Fire Extinguishers on board the Netherlands Flag Ships | 2004/12/03 | SVD |
| 609 | ----- No English version ----- | 2004/11/26 | MCD |
| 608 | Introduction of the outcomes of MEPC 52 | 2004/11/22 | XAD |
| 607 | Measures by ClassNK in response to Instructions issued by the Malta Maritime Authority | 2004/11/09 | XAD |
| 601 | USCG PSC Checklist for the implementation of the ISPS Code | 2004/09/24 | SMD |
| 600 | Medical Oxygen Bottles for Ship's Hospital for the Netherlands flagged vessels | 2004/09/17 | EQD |
| 599 | Thickness measurement record | 2004/09/15 | DMD |
| 597 | Phase-Out of Single Hull Oil Tankers and CAS | 2004/09/01 | SVD |
| 596 | Carriage Requirements of Automatic Identification System (AIS) for Singapore Flag Non-Convention Ships | 2004/08/27 | EQD |
| 595 | ----- No English version ----- | 2004/07/30 | MCD |
| 593 | ----- No English version ----- | 2004/07/28 | EQD |
| 592 | MARPOL 73/78 ANNEX VI Reg.16 Shipboard Incineration | 2004/07/28 | EQD |
| 591 | Application of Council Directive 96/98/EC on marine equipment as amended, to Cyprus flagged vessels | 2004/07/08 | EQD |
| 590 | Maintenance for High Velocity Vents | 2004/07/05 | SVD |
| 589 | Measures by ClassNK in response to Circular No.1/2004 issued by the Cyprus Government | 2004/07/05 | XAD |
| 588 | Introduction of the outcomes of MSC78 | 2004/06/29 | XAD |
| 587 | Bulk Carrier Safety: Water Level Detection & Alarm System and Dewatering Arrangements for dry spaces and ballast tanks. | 2004/06/17 | SVD |
| 586 | Installation of VDR and AIS on Greek Flag Ships | 2004/06/14 | EQD |
| 583 | Service of Safety Equipment for Marshall Islands flagged ships | 2004/05/18 | EQD |
| 582 | Graphical symbols for Fire Control Plans onboard the Hong Kong flagged vessels | 2004/05/14 | EQD |
| 581 | Condition Assessment Scheme (CAS) for the Marshall Islands flag ships | 2004/05/14 | SVD |
| 580 | Introduction of the outcomes of MEPC51 | 2004/04/22 | XAD |
| 579 | Additional Requirements for Greek flag GMDSS ships | 2004/04/22 | EQD |
| 578 | Emergency escape breathing devices (EEBD) onboard the Belize flagged vessels | 2004/04/21 | EQD |
| 577 | Special requirements for life-saving appliances and fire fighting arrangement on board Manx flagged vessels | 2004/04/13 | EQD |
| 576 | Stretchers for Greece flagged ships (revised) | 2004/04/05 | EQD |
| 575 | Spare charges for portable fire extinguishers on Singapore flagged vessels | 2004/04/02 | EQD |
| 573 | SAFETY USE OF RAFTS OR BOATS FOR SURVEY | 2004/03/11 | SVD |
| 570 | Outcome of the IMO Assembly 23rd Session | 2004/03/04 | XAD |
| 569 | Introduction of the outcomes of International Conference on Ballast Water Management | 2004/02/26 | XAD |

| | | | |
|-----|--|------------|-----|
| 566 | Fire fighting equipments onboard the Hong Kong flagged vessels | 2004/01/29 | EQD |
| 565 | Extension of hydraulic pressure test for CO2 bottles and fire extinguishers of non-passenger vessel | 2004/01/23 | SVD |
| 561 | Amendment of IACS Unified Requirements for surveys for Bulk Carrier UR Z10.2 (rev.15) | 2003/12/26 | SVD |
| 558 | Amendments to Class Notations & Descriptive Notes for Class Characters according to the Amendments to the ClassNK Rules the Survey and Construction of Steel Ships | 2003/12/19 | CLD |
| 557 | Introduction of the outcomes of MEPC50 | 2003/12/12 | XAD |
| 556 | Requirements to increase the integrity of fore deck fittings for dry cargo ships | 2003/12/12 | SVD |
| 555 | Guidelines for partially weathertight hatchway covers on board containerships (MSC/Circ.1087) | 2003/12/12 | EQD |
| 553 | Enhanced Survey of Indian flagged Oil tankers and Bulk Carriers | 2003/11/10 | SVD |
| 552 | Crew accommodation for Hong Kong flagged vessels | 2003/10/28 | EQD |
| 546 | Manual operation for boilers and thermal oil heaters manufactured by Miura Co., Ltd. | 2003/09/04 | MCD |
| 543 | Periodic servicing of launching appliances regarding Greek flagged vessels | 2003/08/15 | EQD |
| 542 | Introduction of the outcomes of MEPC49 | 2003/08/08 | XAD |
| 538 | Bulk Carrier Safety (Updated version of ClassNK Technical Information No. TEC-0507) | 2003/07/08 | XAD |
| 535 | Implementation Date of UR S25 (Rev.1) | 2003/06/27 | XAD |
| 534 | Interval of abandon ship and fire drills regarding Malta flagged cargo ships | 2003/06/27 | EQD |
| 533 | Documents necessary to apply for renewal of a radio station license of a St. Vincent and the Grenadines flag ship. | 2003/06/23 | EQD |
| 532 | Introduction of the outcomes of MSC 77 | 2003/06/18 | XAD |
| 531 | Fire extinguishing systems on Panama flagged vessels | 2003/06/18 | EQD |
| 530 | Review of arrangements to supply heading information at emergency steering positron on board Bahamas flag ships | 2003/06/13 | EQD |
| 529 | Radio Records for Singapore flagged vessels | 2003/06/06 | EQD |
| 528 | EC regulations on prohibition of organotin compound on ships | 2003/05/26 | XAD |
| 527 | ----- No English version ----- | 2003/05/26 | SVD |
| 526 | Fire protection for external high pressure fuel delivery lines between high pressure fuel pumps, fuel injectors, and fuel oil piping (Except Japanese flag ships) | 2003/05/26 | SVD |
| 524 | Validity of approval to use fire protection materials approved under former fire test procedures | 2003/05/15 | EQD |
| 521 | ClassNK provisional interpretations for fixed local application fire-fighting system | 2003/05/15 | EQD |
| 519 | Recall of anti-travel sickness (anti-seasickness) medicine | 2003/05/01 | EQD |
| 517 | Crew Accommodation for the Marshall Islands flag ships | 2003/04/15 | EQD |
| 516 | Shipboard Oil Pollution Emergency Plan (SOPEP) | 2003/04/15 | MCD |
| 515 | EC type-examination and other Conformity assessments under Council Directive 96/98/EC on Marine Equipment, as amended | 2003/04/15 | EQD |
| 514 | Cargo handling appliances for the Marshall Islands flag ships | 2003/04/15 | EQD |
| 510 | Maintenance, inspection and tests of fire-protection and fire fighting systems on board Kuwait-registered ships | 2003/04/01 | SVD |
| 509 | Maintenance and Inspection of Oil Filtering Equipment and Oil Content Meter Taking Account of PSC Inspections | 2003/04/01 | SVD |
| 508 | For ships other than ships flying the Japanese flag, amendments to the form of certificate of fitness for ship carrying dangerous goods, and etc. | 2003/04/01 | EQD |
| 506 | Fire extinguishing arrangement for paint and flammable liquid lockers on Marshall Islands flagged vessels | 2003/04/01 | EQD |
| 503 | Special requirements for emergency escape breathing device regarding Marshall Islands and Mauritius flagged vessels (related to SOLAS Chapter II-2 as amended in 2000) | 2003/02/15 | EQD |
| 502 | Release of Survey Status Information of ClassNK Ships | 2003/02/15 | XAD |

| | | | |
|-----|--|------------|-----|
| 501 | Boat drills for Greek flagged vessels | 2003/02/15 | EQD |
| 500 | Surveys and Certification for the Singapore flagged Tankers of 500GT and upwards engaged on Singapore 30-mile limit voyages | 2003/02/15 | XAD |
| 498 | Introduction of the outcomes of MSC 76 | 2003/01/15 | XAD |
| 496 | Measures by ClassNK in response to "International Convention on the Control of Harmful Anti-Fouling Systems on Ships" | 2002/12/15 | SVD |
| 494 | Introduction of the outcomes of MEPC 48 | 2002/12/15 | XAD |
| 491 | Registration of GMDSS IDs of Singapore Flag Ships | 2002/11/15 | EQD |
| 489 | Amendments to COLREG (Convention on the International Regulations for Preventing Collisions at Sea, 1972) | 2002/11/15 | EQD |
| 488 | Special requirements for emergency escape breathing device regarding Kuwait flagged vessels (related to SOLAS Chapter II-2 as amended in 2000) | 2002/10/25 | EQD |
| 487 | CAS(Condition Assessment Scheme)under Amendments to regulation 13G of MARPOL Annex I | 2002/10/25 | SVD |
| 484 | Inspection of Lifiable Car Decks of Pure Car Carriers | 2002/10/11 | SVD |
| 481 | Revised regulation on survey of cargo handling appliances for Cypriot flag ships | 2002/10/11 | EQD |
| 480 | Special requirements for emergency escape breathing device regarding Vietnam flagged vessels (related to SOLAS Chapter II-2 as amended in 2000) | 2002/09/25 | EQD |
| 479 | Measures by ClassNK in response to Circular No.19/2002 issued by the Cyprus Government | 2002/08/25 | XAD |
| 478 | Application for emergency escape breathing device and booklets for Japanese ships (including existing and new ships which are not engaged on international voyages) required by SOLAS chapter II-2 as amended in 2000. | 2002/08/25 | EQD |
| 474 | Revised regulation on survey of cargo handling appliances for Greek flag ships | 2002/08/25 | EQD |
| 473 | Servicing of Inflatable Liferrafts on board Singapore-registered Ships | 2002/08/01 | SVD |
| 471 | Carriage Requirements for GPS receivers on board the Malta Flag Ships | 2002/07/30 | EQD |
| 468 | Introduction of the outcomes of MSC 75 | 2002/07/10 | XAD |
| 466 | Guidelines on Ergonomic Criteria for Bridge Equipment and Layout applicable to Hong Kong Flag Ships | 2002/06/28 | EQD |
| 457 | IMO the 47th session of the Maritime Environment Protection Committee (Agendas concerning technical issues affecting ship's structure) | 2002/05/25 | XAD |
| 456 | Burst casualties of air bottles of a self-contained air support system of over-10-years-old fire-protected lifeboats after installation and inspections / recording | 2002/05/25 | SVD |
| 454 | Arrangement of liferafts regarding Singapore flagged vessels | 2002/04/30 | EQD |
| 452 | Prohibition of the Use of HCFC (R22 etc.) Refrigerants for Refrigerating or Air Conditioning Systems, installed in the Ships flying the Flag of Cyprus | 2002/04/12 | MCD |
| 451 | Eight measures taken by IACS for improving Bulk carrier safety | 2002/04/12 | XAD |
| 449 | The Intersessional meeting of the MSC on Maritime Security - Accelerated application scheme for AIS and other security measures | 2002/04/12 | XAD |
| 448 | Outcome of the IMO Assembly 22nd Session | 2002/04/12 | XAD |
| 446 | Changeover in Geodetic Datum of Nautical Charts issued from Hydrographic Department of Japan Coast Guard to the World Geodetic System (WGS-84) and matters to be attended | 2002/04/01 | EQD |
| 445 | Reporting by Surveyors of Evidence of Possible Safety Management System Failures | 2002/03/29 | SMD |
| 444 | ----- No English version ----- | 2002/03/25 | SVD |
| 442 | ----- No English version ----- | 2002/03/25 | SVD |
| 441 | "Launching at 5 knots" test of lifeboats and rescue boats on board the Bahamas flag ships | 2002/03/25 | SVD |
| 440 | Approved Companies for Shore-based Maintenance of GMDSS Radio Installations and for Inspection of Satellite EPIRBs, and Periodical Inspection and Report of Satellite EPIRBs on board the Greek Flag Ships | 2002/03/25 | EQD |
| 434 | Fire protection for external high pressure fuel delivery lines between the high pressure fuel pumps and fuel injectors, and fuel oil piping | 2002/02/05 | SVD |
| 433 | Certificates to be held by radio personnel on and after 1 February 2002 on board Hong Kong flagged GMDSS ships | 2002/01/04 | EQD |

| | | | |
|-----|--|------------|-----|
| 432 | "Launching at 5 knots" test of lifeboats and rescue boats at sea trial | 2001/12/20 | SVD |
| 427 | Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports | 2001/11/30 | SVD |
| 426 | IMO MSC Circular relating to ISM Code "Guidance on Fatigue Mitigation and Management" | 2001/11/09 | SMD |
| 422 | Application of Council Directive 96/98/EC on marine equipment as amended, to Maltese flagged vessels | 2001/10/18 | EQD |
| 419 | Introduction of the outcome of MSC 74 | 2001/09/13 | XAD |
| 416 | Observance of Procedures and Display of Flow Diagrams for Responding to Digital Selective Calling(DSC) Distress Alerts on Hong Kong Registered Ships | 2001/09/06 | EQD |
| 415 | Carriage of dangerous goods by Cyprus flag ships | 2001/08/24 | EQD |
| 413 | IACS Recommendation relating to ISM Code "A Guide to Managing Maintenance" | 2001/07/30 | SMD |
| 411 | Special requirements for Swiss flag ships | 2001/07/13 | SVD |
| 406 | IMO conventions to enter into force in 2002 (Part 3) (Refer to NK Technical Information No. 396) | 2001/06/18 | XAD |
| 405 | Piping Arrangement of Bilge Discharge from Machinery Spaces through Oily Water Separators | 2001/07/15 | SVD |
| 404 | Mandatory instruments adopted at 46th Session of IMO's Marine Environment Protection Committee (MEPC46, April 2001) ? Acceleration of phasing out scheme of existing single hull tankers | 2001/06/19 | XAD |
| 400 | Halon Fire Extinguishing Systems onboard , St. Vincent and the Grenadines flag vessels | 2001/05/30 | XAD |
| 389 | ----- No English version ----- | 2000/12/20 | SVD |
| 387 | Machinery Verification Runs at the time of drydocking and at the completion of significant repairing | 2000/12/15 | SVD |
| 383 | Requirements adopted by IMO at MEPC 45 | 2000/11/16 | XAD |
| 377 | Oil Analysis as Part of the Preventive Maintenance System for Oil Lubricated Propeller Shafts | 2000/09/21 | SVD |
| 376 | Implementation of recently adopted Conventions by IMO. | 2000/09/14 | XAD |
| 374 | Partial Exemption from the Requirements for GMDSS for Greek Flag GMDSS Ships Engaging on Voyages in the Mediterranean and Black Sea | 2000/09/01 | EQD |
| 373 | Inflatable liferafts, marine evacuation systems and hydrostatic release units on board Greek flag ships | 2000/08/25 | EQD |
| 372 | Launching appliance and lifeboat on-load release gear on board Malta flag ships | 2000/08/25 | EQD |
| 365 | Introduction of HSSC to the Maltese vessels | 2000/06/19 | XAD |
| 364 | The exemption from damage stability requirements for the existing bulk carriers | 2000/06/15 | SVD |
| 363 | Introduction of HSSC to the Maltese vessels | 2000/06/02 | XAD |
| 361 | Survey of Life-saving Appliances for the Netherlands Flag Ships | 2000/03/16 | EQD |
| 359 | Procedure for Responding to Digital Selective Calling (DSC) Distress Alerts by Hong Kong Registered Ships. | 2000/05/16 | EQD |
| 358 | Gross Tonnage for Determination of Application of GMDSS Requirements to Panamanian Ships | 2000/04/28 | EQD |
| 357 | Overhauling and operational test of lifeboat on- Load release gear for Bahamas flag ships | 2000/04/25 | EQD |
| 356 | Resolutions adopted by IMO Assembly at its 21st Session | 2000/04/05 | XAD |
| 355 | ----- No English version ----- | 2000/03/31 | SVD |
| 354 | An amendment to the Regulations of California for Oil Spill Prevention and Response | 2000/04/07 | XAD |
| 350 | Examination and certification of shipboard incinerators | 2000/01/21 | EQD |
| 349 | Interpretations of Chapter III of 1996 Amendments to 1974 SOLAS and LSA Code, and Survey / Testing Procedures | 2000/01/21 | EQD |
| 347 | Guideline for issuance of the Statutory Certificates under the Harmonized System of Survey and Certification (HSSC) | 2000/01/20 | SVD |
| 345 | Treatment of indent on deck crane or derrick boom | 1999/12/24 | SVD |
| 338 | Safe Working Load of the cargo handling appliances under SI units | 1999/11/15 | EQD |

| | | | |
|-----|--|------------|-----|
| 335 | Rescue boat launching appliances on board Netherlands Flag Ships | 1999/10/12 | EQD |
| 333 | Requirements to be met by vessels entering into Greek Ports carrying solid cargoes in bulk | 1999/10/29 | XAD |
| 332 | Cyprus Requirements with regard to Fire Control & Life Saving Appliances Plans | 1999/11/01 | XAD |
| 325 | Rescue boat launching appliances on board Netherlands Flag Ships | 1999/08/24 | EQD |
| 322 | Maintenance of Sea Water/Sanitary Piping in Engine Rooms and Sea Water Piping on Weather Decks | 1999/08/04 | SVD |
| 318 | Corrective action required by PSC with regard to ISM-related non-conformity caused by poor maintenance of ship and its equipment | 1999/07/01 | SMD |
| 314 | Training and drills of Lifesaving on board Netherlands Flag Ships | 1999/05/28 | EQD |
| 313 | Canadian Code to be applied to ships that carries timber deck cargoes into or out of Canada | 1999/06/01 | EQD |
| 312 | Remedy of mechanical and electrical damages occurred in Greece | 1999/05/21 | SVD |
| 310 | Revised cargo gear regulation of Australia | 1999/05/10 | EQD |
| 307 | MARPOL73/78 Annex V "Regulations for the prevention of pollution by garbage from ships" | 1999/04/19 | MCD |
| 306 | Requirements for GAS Carriers which will enter Indian Ports | 1999/04/07 | SVD |
| 290 | Examinations, Testing and Certification Requirements of USA OSHA for Cargo Gears of Ships Loading/Unloading at USA Ports | 1998/12/15 | EQD |
| 289 | Abstract of 96 SOLAS and LSA Code | 1999/12/16 | EQD |
| 280 | Fire Extinguishing Arrangement for Paint Lockers and Flammable Liquid Lockers of Liberian Flag Ships | 1998/08/26 | EQD |
| 275 | Radio Logbooks Required on Board Liberian and Greek Flag GMDSS Ships | 1998/08/12 | EQD |
| 238 | Application of ILO Conventions to Crew Accommodations of Liberian Ships and Marshall Islands Ships | 1997/12/18 | EQD |
| 235 | Crew Accommodations of Singapore Ships | 1997/11/30 | EQD |
| 208 | Reserve Sources of Energy for GMDSS Radio Equipment on board Greek Flag Ships | 1997/02/25 | EQD |
| 199 | Maintenance for electro-hydraulic cranes | 1996/11/11 | EQD |
| 190 | Positioning of Sidelights on Hong Kong Flag Container Ships | 1996/07/25 | EQD |
| 185 | Suspension of Class | 1996/06/01 | CLD |
| 172 | A pump used both for an oily water separator and sludge transfer | 1995/12/21 | SVD |
| 53 | Annual Inspections of Crew Lifts Fitted on board Greek Flag Ships | 1986/11/05 | EQD |

(Disclaimer)

ClassNK Technical Information is provided only for the purpose of supplying current information to readers. Nippon Kaiji Kyokai, its officers, employees and agents or sub-contractors do not warrant the accuracy of the information contained herein and are not liable for any loss, damage or expense sustained whatsoever by any person caused by use of or reliance on this information.

[▲TOP](#)