Subject

Special requirements for emergency escape breathing device regarding Marshall Islands and Mauritius flagged vessels (related to SOLAS Chapter II-2 as amended in 2000)



No.TEC-0503Date15 February 2003

To whom it may concern

The Marshall Islands Government and the Mauritius Government have noticed ClassNK of the special requirements for emergency escape breathing device on board the Marshall Islands and Mauritius flagged vessels as follows.

Marshall Islands

There should be, as a minimum, two EEBDs on each level (at each deck or platform level) of the machinery space. If a machinery space contains an enclosed primary escape trunk having a door at each level, only one EEBD need be located on each level.

Mauritius

- 1. If the ship has a sprit house, the minimum two EEBDs per house should be provided.
- 2. The number of EEBD in the machinery spaces should be as follows.
 - (1) Two sets in the control room.
 - (2) One set by each escape ladder.
 - (3) Notwithstanding the requirements specified in (1) and (2), a minimum of four sets should be provided.
- 3. Spare EEBD should be as follows.
 - (1) At least one spare EEBD set should be provided on board ships with ten or less EEBDs.
 - (2) Ships with eleven to twenty EEBD on board should carry at least two spare devices.
 - (3) Ships with more than twenty EEBDs on board should carry spare equal to at least 10% of the total EEBD but not more than four spares will be required.
- 4. At least one set of EEBD will be required for the purpose of crew training. The training devices should be stowed separate from the spare EEBD and properly marked "Training EEBD Set".

For any questions about the above, please contact:

NIPPON KAIJI KYOKAI (ClassNK)

Material and Equipment Department, Administration Center, Head Office

Address: 4-7, Kioi-cho, Chiyoda-ku, Tokyo 102-8567, Japan

Tel.: +81-3-5226-2020

Fax: +81-3-5226-2057

E-mail: eqd@classnk.or.jp

NOTES:

- ClassNK Technical Information is provided only for the purpose of supplying current information to its readers.
- ClassNK, its officers, employees and agents or sub-contractors do not warrant the accuracy of the information contained herein and are not liable for any loss, damage or expense sustained whatsoever by any person caused by use of or reliance on this information.
- Back numbers are available on ClassNK Internet Homepage (URL: www.classnk.or.jp).