Subject

Postponement of the implementation of IACS CSR for Double Hull Oil Tankers, July 2008 "Rule Change Notice No. 1"



No. TEC-0776 Date 14 July 2009

To whom it may concern

- 1. ClassNK partly amended Part CSR-T of the Rules and published Rule No. 14 (for Japanese-flagged ships) and Rule No.19 (for non Japanese-flagged ships) on 15 April 2009 based on IACS CSR for Double Hull Oil Tankers, July 2008 "Rule Change Notice No. 1" (hereinafter referred to as RCN1 of IACS Tanker CSR) adopted by IACS in January of 2009. The amendments to Part CSR-T were to be applied to ships contracted for construction on or after 1 July 2009.
- 2. Just before the implementation date of RCN1 of IACS Tanker CSR, however, IACS received a strong request from an international industry organization for re-consideration of the provision or further explanation of the technical background regarding the amendments related to the minimum thickness requirements of bottom and side shell plates included in RCN1 of IACS Tanker CSR. After extraordinary and controversial debates, the IACS Council eventually decided on 29 June 2009 by majority vote to carry out a necessary technical study on the relevant provision for further review of RCN1 of IACS Tanker CSR and to postpone its implementation until such time the technical study is completed. (Please refer to the Note of the attachment 1.)
- 3. IACS CSR and its amendments have to be uniformly implemented as Class Rules, and therefore once IACS decided to postpone the implementation of the RCN1, ClassNK has to postpone the implementation of the amendments to Part CSR-T of the Rules following the IACS decision.
- 4. ClassNK will urgently take necessary formal procedures, which may require a couple of months, to change the implementation date of 1 July 2009. This is an exceptional case and ClassNK would greatly appreciate your understanding regarding this matter.

(To be continued)

NOTES:

- ClassNK Technical Information is provided only for the purpose of supplying current information to its readers.
- ClassNK, its officers, employees and agents or sub-contractors do not warrant the accuracy of the information contained herein and are not liable for any loss, damage or expense sustained whatsoever by any person caused by use of or reliance on this information.
- Back numbers are available on ClassNK Internet Homepage (URL: www.classnk.or.jp).

For any questions about the above, please contact:

1. General

NIPPON KAIJI KYOKAI (ClassNK)

External Affairs Division, Administration Center, Head Office Address: 4-7 Kioi-cho, Chiyoda-ku, Tokyo 102-8567, Japan

Tel.: +81-3-5226-2038 Fax: +81-3-5226-2024 E-mail: xad@classnk.or.jp

2. Handling of the RCN1 of IACS Tanker CSR

Hull Department, Administration Center, Head Office

Address: 4-7 Kioi-cho, Chiyoda-ku, Tokyo 102-8567, Japan

Tel.: +81-3-5226-2018 Fax: +81-3-5226-2019 E-mail: hld@classnk.or.jp

3. Contents and applicable software of the RCN 1 of IACS Tanker CSR

Development Department, Research Center, Head Office

Address: 1-8-3 Ohnodai, Midori-ku, Chiba 267-0056, Japan

Tel.: +81-43-294-6672 Fax: +81-43-294-6699 E-mail: dvd@classnk.or.jp

Attachment:

 IACS Common Structural Rules for Double Hull Oil Tankers, July 2008 Rule Change Notice No. 1 January 2009

Common Structural Rules for Double Hull Oil Tankers, July 2008

Rule Change Notice No.1 January 2009

Notes: (1) Based on further input from industry, IACS Council has decided to postpone the implementation of this RCN 1 until such time as a necessary technical study is completed.

For further details of the technical study, please contact IACS CSR Secretariat at csr@iacs.org.uk.

Copyright in these Common Structural Rules for Double Hull Oil Tankers is owned by:

American Bureau of Shipping Bureau Veritas China Classification Society Det Norske Veritas Germanischer Lloyd Korean Register of Shipping Lloyd's Register Nippon Kaiji Kyokai Registro Italiano Navale

Russian Maritime Register of Shipping

Copyright © 2006

The IACS members, their affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as the 'IACS Members'. The IACS Members, individually and collectively, assume no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant IACS Member entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.